PleasureCraft Condition Report

vero marine

Inspection and Report must be completed by an independent, suitably qualified Surveyor, Shipwright or Boatbuilder, with any costs being met by the Purchaser/Owner

General Details

Client Name [redacted] Email [redacted]

Phone [redacted] Address [redacted] Auckland.

Inspection Date 20/5/24

Inspection Place Northcote Pt, Gold Hole. Birkenhead Yacht Club.

Slipped for Inspection? yes / no (Please circle)

Vessel Name BLUE GRASS

Vessel Type Cruising Yacht

Design and Model 1974 John Lidgard

Builder J Lidgard Yachts & Co. Ltd.

Launched 1977

Approximate Dimension (m):

Length 11.6 Beam 3.5 Draft 1.8m

Engine Make Beta Marine Model 50hp.

Year 2018 Hours 250

Construction Materials:

Hull triple diagonal Kauri Deck plywood Cabin plywood

Code for each applicable section: G = good; S = serviceable; R = requires attention; / = not applicable

Hull Condition

	Code	Comments
Exterior - underwater		
Hull	G	Tap tested, soundings & visual inspections all good
Keel	G	"
Keel Join	G	"
Antifoul Condition	G	"
Rudder/s	G	"
Shaft/s	G	new prop shaft 2018 - as new cond.
Propeller/s	G	new propeller 2018 - as new cond.
Skin Fittings	G	
Exterior - topsides		
Hull	G	Tap tested, soundings & visual inspection all good
Boarding Platform	N/A	
Hull/Deck Join	G	Solid timber gunwale.
Bollard / cleats	G	
Stanchions - safety lines	G	all robust, noted missing through bolts x2 stanchions aft.
Windlass	G	operational
Cockpit Area	G	

Exterior - cabin		
Windows and screens	G	
Exterior - other		
Flying Bridge	N/A	
Canopies & Canvas	N/A.	
Interior - shell		
Overall Watertightness	G	
- boundary doors	N/A	
- hatches	G	
- windows	G	re-caulked
- yacht companionway	G	
Bulkheads	G	
Guard Rails	G	
Scantlings (structural members)	G	
Keel bolts - fastenings	G	
Skin fittings/ sea cocks / valves	G	all new w/sea cock values · & colars
Bilge Condition	G	
Interior - cabin		
Toilet arrangement	G	
Basin & shower	G	
Mast step	G	
Sides - top	G	
Interior - other		
Deck head	G	
Side & Fore decks	G	

Electrical / Electronics & Comms Gear

	Code	Comments
Navigation Lights	R.	Requires stern light
Wiring - Condition	G	all new throughout.
Batteries - Condition	G	2020 New
Batteries - Security	G	independent box w/strap down.
Burglar Alarm	N/A	
Operating Instruments	G	
Auto Pilot	N/A.	
VHF/s	G	fixed & handheld
SSB	N/A	
GPS	G	Garmin
Plotter	G	Garin
Radar	N/A	
Depth Sounder	G	Garmin, 2nd sounder in cockpit BNG.
EPIRB	G	current to NOV 2028

Mechanical Condition

	Code	Comments
Engine Installation	G	new install 2018
Engine beds	G	robust design & sound condition
Engine controls	G	good feedback.
Drive train/s	G	updated & in good condition.
Exhaust/s	G	new pipes, hose clips good
Fuel lines filters	G	all new fuel lines filters, cleaned tanks 2018
Fuel shut off valves	G	Valve for ea. tank x2
Fuel tanks filters	G	cleaned every service, new 2018
Fuel tank vents	G	into cockpit
Domestic Plumbing	G	all new
Holding Tanks	G	50litre. all new
Bilge pumps - Adequate	G	x1 electric, x1 manual
- Discharges	G	all new hoses, skin fittings, seacocks.
- Float Switches	G	x1 always on
Steering Gear	G	Good
Emergency Tiller	G	hydrovane independent propulsion & secondary rudder + wooden emergency tiller.

LPG

	Code	Comments
Installation to NZ Standards	G ~~R~~	~~requires bigger drain hole 19mm. Seal off locker~~ 03/01/25 Now Meets standard GBusfield

Safety Equipment

	Code	Comments
Anchor & warp	G	60metres chain 35lbs.
Spare Anchor & warp	G	large anchor, chain & rope fwd
Flares - current to	G	12/26 6pack
Fire Extinguishers - type / current to	G	1Kg Dry Powder x2 in green, 1Kg Dry chemical in Dry Powder
- adequate for the vessel?	G	dates not specified.
Fire Extinguisher fixed system	N/A	
Lifejackets	G	x3 foam x4 inflatable adults
Life Buoys	G	x1
Safety harness	G	x2
Life raft	N/A	
Dinghy / tender	G	3.1hp Mercury, Maxon 2.8m soft bottom inflatable.
Outboard	G	3.1hp Mercury rear new 2018
Charts, Navigational & course-plotting materials	G	Nav charts. compass. Garmin plotter

Mast Spars Sails Rigging

	Code	Comments
Mast/s year installed	G	Original, no sign of corrosion
Boom/s	G	
Mast step	G	Robust design in good condition
Standing rigging	G	updated 2020
Running rigging	G	updated 2020
Chain plates	G	Robust design reinforced, all sound
Sheet winches	G	Good condition.
Sails	G	

Note: Inspection of above items is limited to a visual from the deck.

Date rigger last inspected mast, spars and rigging: ___ / ___ / ___
November 2020

Vessel Stability

Are you aware of any Stability Tests which have been undertaken:

- on this vessel? **yes ~ no**
- on this vessel design? **yes ~ no**

Comment: 50% of weight in bottom of keel, Known capabilities of Design.

Vessel Alterations

Has the vessel been altered since it was built? **yes ~ no**

If yes, were the alterations carried out in accordance with the requirements of a naval architect? **yes ~ no** N/A.

Vessel Operating Limit

Do you consider the vessel to be in a safe and seaworthy condition for use up to 200 nautical miles from the North or South Islands of New Zealand? **yes ~ no**

If no, please provide comments in the section below and advise what you consider the limit should be: ____ nautical miles.

Other Comments / Signature

This report is not classed as a Full Condition Survey and is purely for underwriting purposes. We accept that all care has been taken but no responsibility is accepted for latent or other defects.

Copyright exists and the detail and content are the exclusive property of Vero Marine Insurance.

Any comments or recommendations you wish to make?
Yacht is kept in good condition with many updated parts throughout.

Company: Barclay Yachts Ltd.
Name: George Burfield
Date: 20/5/24
Qualifications: NZ Certificate in Boat Building
Phone: 022 029 3036
Email: info@barclayyachts.co.nz
Signed: G Burfield